



Front View



Loose/broken/delaminated  
Damage/wear/hole

Previous repair  
Replaced piece


Rear View



Missing  
Spindles not original to desk

Add-ons  
Inscriptions


Right Side



■ Loose/broken/delaminated  
■ Damage/wear/hole

■ Previous repair  
■ Replaced piece

Left Side




■ Missing  
■ Spindles not original to desk

■ Add-ons  
■ Inscriptions

*No cross-banded veneer*

Top



← No inkwell opening

■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece


■ Missing



■ Spindles not original to desk



■ Add-ons

■ Inscriptions


Bottom





 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece

Bottom




 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front




■ Loose/broken/delaminated  
■ Damage/wear/hole

■ Previous repair  
■ Replaced piece


■ Missing  
■ Spindles not original to desk

■ Add-ons  
■ Inscriptions

Inside Surface of Left Drawer Side



Inside Surface of Right Drawer Side



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece

Missing


Spindles not original to desk

Add-ons

Inscriptions

Rear Surface of Drawer Back

Front Surface of Drawer Back



■ Loose/broken/delaminated  
■ Damage/wear/hole


■ Previous repair  
■ Replaced piece



■ Missing  
■ Spindles not original to desk



■ Add-ons  
■ Inscriptions




Upper Surface of Drawer Bottom





 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece

Lower Surface of Drawer Bottom





 Missing  
 Spindles not original to desk



 Add-ons  
 Inscriptions





Outside Surface, Right Drawer Side


Outside Surface, Left Drawer Side



 Loose/broken/delaminated  
 Damage/wear/hole

 Previous repair  
 Replaced piece

 Missing  
 Spindles not original to desk

 Add-ons  
 Inscriptions